

Detailed Vehicle Specification

VIN	AFAPXXMJ2PRA74815				
Vehicle Line	T/RB	Market Derived Code	F		
Body Cab	T/BC	Ver. Series	T/R4		
Drive Type	T/H				
PLT CD	BQ	TRS CD	T/EU	ENG CD	T/RBF
Production Date	07-MAR-2024	Warranty Start Date	31-MAY-2024		
Selling Dealer	91213	Selling Country	ZAF		

GSAR Claim Key		Trx Code	Time In Service	Labor Hours	Dealership	DIST (Miles)	Repair Date	Prefix	Base	Suffix	Doc
Details	1568702	20N01	5	0.7	FORD AMANZIMTOTI	1997	03-OCT-2024	N1WZ	17618	C	B106481
	Customer Comments		Washer Bottle Leaking. (0.5)								
	Tech Comments		Brandon Ngcobo: Found during service that windscreen washer bottle is leaking water Checked PTS for available TSB/GSB/SSM related to concern - None available Removed rhs fender liner and inspected windscreen washer bottle for any signs of damage or cracks - No damage found on bottle Found that water is leaking from windscreen washer bottle mounting bolts Tightened bolts but problem persists Cause of concern is a part failure on the windscreen washer bottle assembly leading to water leaking out from bottle when filled								
Details	1594072	24B49	5	0.3	FORD AMANZIMTOTI	2016	09-OCT-2024	*	*	*	B107101
	Customer Comments		Campaigns: 24B49: 3.0L LION ENGINE OIL OVERFILL (0.3)								
	Tech Comments		Kayle Naidoo: In all the affected vehicles, it may be possible to overfill the engine oil. As per the Owners Manual, it is necessary to wait for a minimum of 15 minutes after the engine has been turned off before checking the oil level. An overfilled engine oil level may result in a sudden unintended increase in engine speed followed by excessive smoke and possible noise. If the engine system detects an unintended increased engine speed, the transmission automatically decouples and will prevent drive going to the wheels. The powertrain control module will shut off the engine.								
Details	2348542	8159S	7	1.5	MCCARTHY FORD SILVER LAKES	8857	23-DEC-2024	*	MAINT	*	F145271
	Customer Comments		15 000 km service								
	Tech Comments		15 000 km service								
Details	3733829	8159S	12	2.6	MCCARTHY FORD SILVER LAKES	18387	09-MAY-2025	*	MAINT	*	F170841
	Customer Comments		CARRY OUT 30 000KM SERVICE								
	Tech Comments		CARRIED OUT 30 000KM SERVICE								
Details	5405114	8159S	17	1.8	MCCARTHY FORD SILVER LAKES	28602	03-OCT-2025	*	MAINT	*	F199851
	Customer Comments		45 000 KM SERVICE								
	Tech Comments		45 000 KM SERVICE								
Details	5382503	24P37	17	1.1	MCCARTHY FORD SILVER LAKES	28602	03-OCT-2025	*	*	*	B289842
	Customer Comments		INSPECT ALL GLOW PLUGS, AND REPLACE SUSPECT (FAILED) PARTS								
	Tech Comments		INSPECT ALL GLOW PLUGS, AND REPLACE SUSPECT (FAILED) PARTS								
Details	6682441	8159S	21	2.6	MCCARTHY FORD SILVER LAKES	37821	29-JAN-2026	*	MAINT	*	F222431
	Customer Comments		CARRY OUT 60 000KM SERVICE								
	Tech Comments		CARRIED OUT 60 000KM SERVICE								