

OASIS RESULTS:AFAPXXMJ2PNA85665		ZAF - EN	07-OCTOBER-2025 / 09:17:51 EST LOCAL TIME: 7-OCTOBER-2025 / 3:17:52 PM
▲ VEHICLE INFORMATION <div> VEHICLE DESCRIPTION: 2023 P703M RANGER BODY STYLE: Crew Cab ENGINE: 2.0L CR TC DSL PANTHER C ENGINE CALIBRATION: TRANSMISSION: 10 Speed Auto Transmission (10R80) FUEL TYPE: Diesel Sold to Fleet: NO </div>		VERSION/SERIES: WILDTRAK #4 SERIES DRIVE TYPE: 2 WHL R/H REAR DRIVE-HIGH RIDE AXLE RATIO: 3.55 Ratio AXLE CODE: WHEEL SIZE: 18 X 7.5 ALLOY WHEEL TIRE: Retail sales type: R	ADDITIONAL INFORMATION PAINT COLOR: Frozen White PAINT CODE: GROSS VEHICLE WEIGHT: CALCULAT GVW OR PICK FRM TABLE RADIO: ASIAN RADIO FREQUENCY SYNC VERSION: GEN4 VHR ACTIVATED: MODEM: 4G
▲ OUTSTANDING FIELD SERVICE ACTIONS			
NO CAMPAIGN MESSAGE(S) FOUND			
▲ WARNING MESSAGES			
▲ GENERAL WARRANTY INFORMATION			
WARRANTY START DATE: 23-January-2023		BUILD DATE: 08-December-2022	RELEASE DATE: 10-January-2023
SALE MILEAGE:			
▲ WARRANTY COVERAGE			
NO WARRANTY COVERAGE MESSAGE(S) FOUND			
▲ EXTENDED COVERAGES			
NO ESP INFORMATION AVAILABLE			
8159 - EXPIRED			
STANDARD DEDUCTIBLE: 0 ZAR		OWNER NAME: VALUED CUSTOMER	OPTIONS:
EXPIRATION DATE: 02/23/2029		DISTANCE: 91500	RENTAL: 0 UP TO 0 DAYS
TOWING: 0 ZAR		CONTRACT SOLD BY: ZAF 90661	

[illegible]

Details	1889588	23P10	11	0.3	TWENTY FOUR MOTORS ERMELO	28524	08-DEC-2023	*	*	*	4291922
	Customer Comments	C- Campaigns: 23P10: POWER FOLD DOOR MIRROR NOISE									
	Tech Comments	C- CAMPAIGN 23P10 C- GREASE MIRRORS AS PER CAMPAIGN 23P10 23P10B = 0.3									
Details	1887000	8159S	11	1.8	TWENTY FOUR MOTORS ERMELO	28524	08-DEC-2023	*	MAINT	*	429191
	Customer Comments	45 000KM SERVICE									
	Tech Comments	45 000KM SERVICE									
Details	2852675	8159S	14	2.6	EASTERN CAPE MOTORS WILLIAM MOFFETT	37479	29-FEB-2024	*	MAINT	*	B138451
	Customer Comments	Carry out 60 000km service RTR -Cs									
	Tech Comments	Completed 60 000km service									
Details	4110763	23L07	17	0.2	EASTERN CAPE MOTORS WILLIAM MOFFETT	48429	11-JUN-2024	*	*	*	B154393
	Customer Comments	Inspect for and insert (if required) Towing a Trailer Precautions Supplement Booklet									
	Tech Comments	Inspect for and insert (if required) Towing a Trailer Precautions Supplement Booklet									
Details	4107583	8159S	17	1.5	EASTERN CAPE MOTORS WILLIAM MOFFETT	48429	11-JUN-2024	*	MAINT	*	B154391
	Customer Comments	75 000 km service - ms									
	Tech Comments	75 000 km service									
Details	9453970	24B33	33	0.4	PARK FORD	65966	15-SEP-2025	*	*	*	275602
	Customer Comments	REMOVE AND INSTALL CHARGE AIR COOLER DUCT									
	Tech Comments	REMOVE AND INSTALL CHARGE AIR COOLER DUCT									