

**GENERAL** 

Botha & Deysel workshop -**Report Name** 

Lb50bsgp

**Client Name** Botha & Deysel workshop

Botha En Deysel Werkswinkel **Assessment Centre** 

Assessor Hugo van Zyl

04-09-2025 16:09:51 **Inspection Date** 

**VEHICLE** 

Year 2023 Reg No Lb50bsgp

Colour Blue

Mf3pb812tpj036212 VIN

Make **HYUNDAI** 

Model CRETA 1.5 EXECUTIVE IVT

**Current Odometer** 72257

**Engine** Not available

**CHECKS & REPORTS** 

**OEM Warranty Active** True **Warranty Details** Details available from dealer

**Aftermarket Warranty** False **Type Of Warranty** N/A

Active

All service intervals completed by Service History Invoices Service History False

OEM Available

**Accident Damage** 

None Major Repair Disclosure None Disclosure

**BODY EXTERIOR** 


**Number Plates** SABS Approved Windscreen Minor Chips

Side Mirrors No Damages or Paint Issues **Door Locks** Good Working Condition


Dents, Scratches and Minor damages or paint issues

Misalignments









Comments

Exter In good shape

STARTING AND CHARGING SYSTEM

Good Working Condition Battery voltage normal 12.6 V Good Working Condition **Battery condition** Battery Voltage Starting 9.6 V Good Working Condition Alternator Charging 13.5v - 15v Good Working Condition

Comments Starting system in order

**ENGINE COMPARTMENT** 

**Bonnet Hinge** Good Working Condition **Bonnet Catch** Good Working Condition **Coolant Level** Good Working Condition **Radiator Cap** Good Working Condition Hoses / Pipes All Functioning, No Leaks **Auxiliary Drive Belts** Good Working Condition **Brake Fluid level** Good Working Condition **Engine oil level and Condition** Good Working Condition Good Working Condition **Power Steering Oil level** Clutch Fluid (if separate) N/A

Oil & Fluid Leaks All Functioning, No Leaks **All Components Secured Safely** Good Working Condition

Comments Engine compartment in order

NTERIOR			
Ignition Lock; switch	Good Working Condition	Front Park Lights	Good Working Condition
Head lights - Dim	Good Working Condition	Head lights - Bright	Good Working Condition
Fog Lights Front	Good Working Condition	Rear Fog Lights	Good Working Condition
Rear Park Lights	Good Working Condition	Daytime Driving Lights	Good Working Condition
Reverse Lights	Good Working Condition	Stop Lights	Good Working Condition
Number Plate Light	Good Working Condition	Hazard Lights	Good Working Condition
LHS Indicator	Good Working Condition	RHS Indicator	Good Working Condition
Interior Lights	Good Working Condition	Controls/Switches	Good Working Condition
Instruments	Good Working Condition	Horn	Good Working Condition
Driver Window Mechanism	Good Working Condition	Passenger Window Mechanism	Good Working Condition
LHS Rear Window Mechanism	Good Working Condition	RHS Rear Window Mechanism	Good Working Condition
Sunroof Operation	N/A	Convertible Roof	N/A
LHS Mirror Adjustment	Good Working Condition	RHS Mirror Adjustment	Good Working Condition
Rear Wiper and Washer	Good Working Condition	Windscreen Wiper and Washer	Good Working Condition
Air Conditioner / HVAC System	Good Working Condition	Radio and Audio System	Good Working Condition
Driver Seat - Seat Belt	Good Working Condition		
Driver Seat – Adjustments	Good Working Condition	Driver Seat – Upholstery	Good Working Condition
Passenger Seat – Seat Belt	Good Working Condition		
Passenger Seat - Upholstery	Good Working Condition	Passenger Seat – Adjustments	Good Working Condition
Rear Passenger Seats – Seat Belt(s)	Good Working Condition		
Rear Passenger Seats – Upholstery	Good Working Condition	Rear Passenger Seats – Adjustments	Good Working Condition
Panels, Covers and Trim Fitment	Good Working Condition	Diagnostic Fault Codes	Good Working Condition
Rear View Mirror	Good Working Condition	Roof Lining Fitment	Good Working Condition
Cabin Heater	Good Working Condition	Carpets and Mats	Good Working Condition
Set Clock	Good Working Condition	Check & Clear Diagnostic Fault Codes	Good Working Condition
Bonnet Release Lever	Good Working Condition		
Comments	Interior in good shape		

BOOT			
Boot lock	Good Working Condition	<b>Boot Hinges</b>	Good Working Condition
<b>Boot Linings</b>	All correctly Fitted	Spare Wheel	More than 20% tread & inflated
Jack	Present & Functioning	Wheel Spanner	Present & Functioning
Security Lock Nut	N/A	Run Flat Repair Kit	N/A
Comments	Boot in order		

UNDER CARRIAGE			
Steering System Play	Good Working Condition	Oil and Fluid Leaks	Good Working Condition
Exhaust Leaks	Good Working Condition		
Shocks (leaks) Front	<b>Good Working Condition</b>	Shocks (leaks) Rear	Good Working Condition
Springs/Suspension Bushes & Links Front	Good Working Condition	Springs/Suspension Bushes & Links Rear	Good Working Condition
Front Brakes – Disc's & Pads	Good Working Condition	Rear Brakes - Disc's & Pads	Good Working Condition
Brake Pipe Fitment	Good Working Condition	Rear Brakes - Drums & Shoes	N/A
Front Wheel Bearings	<b>Good Working Condition</b>	Rear Wheel Bearings	<b>Good Working Condition</b>
Fuel Tank Leaks	Good Working Condition	Fuel Pipe Fitment	Good Working Condition
RF Tyre Tread	More than 50%	RF Tyre Size	Correct as per OEM
LF Tyre Tread	More than 50%	LF Tyre Size	Correct as per OEM
LR Tyre Tread	More than 50%	LR Tyre Size	Correct as per OEM
RR Tyre Tread	More than 50%	RR Tyre Size	Correct as per OEM
		Drive Shafts	Good Working Condition
Comments	Undercarriage In order		

TEST DRIVE			
Noise at Idle (Cold)	Good Working Condition	Excessive fumes/Smoke at idle	Good Working Condition
Final Drive Noise	Good Working Condition	Gearbox Noise	Good Working Condition
Engine Noise	Good Working Condition	Turbo/Super Charger Noise	N/A
Clutch Operation	Good Working Condition	Auto Gearbox Operation	Good Working Condition
Cruise Control/Adaptive	Good Working Condition	Instrument Cluster Functions	Good Working Condition
Warning Lights	Good Working Condition	Overheating	Good Working Condition
Engine Performance	Good Working Condition	Road holding / Stability	Good Working Condition
Brake Operation	Good Working Condition	Brake Noise	Good Working Condition
Brake Shudder	No	Emergency Stop Test / ABS	Good Working Condition
Steering Effort and Play	Good Working Condition	Suspension Noise	No
Vibrations & Harshness over 110km/h	No	Handbrake function	Good Working Condition
Hot Restarting	Good Working Condition	Re-check Diagnostic Fault Codes	No Fault Codes
Comments	Car drives great		

## **GENERAL COMMENTS**