

**GENERAL**

|                   |                                    |
|-------------------|------------------------------------|
| Report Name       | Botha & Deysel workshop - KPR804NW |
| Client Name       | Botha & Deysel workshop            |
| Assessment Centre | Botha En Deysel Werkswinkel        |
| Assessor          | Hugo van Zyl                       |
| Inspection Date   | 05-09-2025 06:54:54                |

**VEHICLE**

|                  |                                           |
|------------------|-------------------------------------------|
| Year             | 2021                                      |
| Reg No           | KPR804NW                                  |
| Colour           | Silver                                    |
| VIN              | AFAPXXMJ2PLY35976                         |
| Make             | FORD                                      |
| Model            | RANGER 2.0D BI-TURBO WILDTRAK A/T P/U D/C |
| Current Odometer | 121000                                    |
| Engine           | YN2LPLY35976                              |


**CHECKS & REPORTS**

|                             |                                                       |                                    |      |
|-----------------------------|-------------------------------------------------------|------------------------------------|------|
| OEM Warranty Active         | False                                                 | Warranty Details                   | N/A  |
| Aftermarket Warranty Active | False                                                 | Type Of Warranty                   | N/A  |
| Service History             | All Service Intervals completed by OEM or Aftermarket | Service History Invoices Available | True |
| Accident Damage Disclosure  | None                                                  | Major Repair Disclosure            | None |

**BODY EXTERIOR**

|                                    |                               |            |                        |
|------------------------------------|-------------------------------|------------|------------------------|
| Number Plates                      | SABS Approved                 | Windscreen | Minor Chips            |
| Side Mirrors                       | No Damages or Paint Issues    | Door Locks | Good Working Condition |
| Dents, Scratches and Misalignments | Minor damages or paint issues |            |                        |

Damage Mark Up



Comments

Exterior in good shape

**STARTING AND CHARGING SYSTEM**

|                                |                          |                                 |                        |
|--------------------------------|--------------------------|---------------------------------|------------------------|
| Battery condition              | Good Working Condition   | Battery voltage normal 12.6 V   | Good Working Condition |
| Battery Voltage Starting 9.6 V | Good Working Condition   | Alternator Charging 13.5v - 15v | Good Working Condition |
| Comments                       | Starting system in order |                                 |                        |

## ENGINE COMPARTMENT

|                                 |                             |                                       |                        |
|---------------------------------|-----------------------------|---------------------------------------|------------------------|
| <b>Bonnet Hinge</b>             | Good Working Condition      | <b>Bonnet Catch</b>                   | Good Working Condition |
| <b>Coolant Level</b>            | Good Working Condition      | <b>Radiator Cap</b>                   | Good Working Condition |
| <b>Hoses / Pipes</b>            | All Functioning, No Leaks   | <b>Auxiliary Drive Belts</b>          | Good Working Condition |
| <b>Brake Fluid level</b>        | Good Working Condition      | <b>Engine oil level and Condition</b> | Good Working Condition |
| <b>Power Steering Oil level</b> | Good Working Condition      | <b>Clutch Fluid (if separate)</b>     | N/A                    |
| <b>Oil &amp; Fluid Leaks</b>    | All Functioning, No Leaks   | <b>All Components Secured Safely</b>  | Good Working Condition |
| <b>Comments</b>                 | Engine compartment in order |                                       |                        |

## INTERIOR

|                                            |                         |                                                 |                        |
|--------------------------------------------|-------------------------|-------------------------------------------------|------------------------|
| <b>Ignition Lock; switch</b>               | Good Working Condition  | <b>Front Park Lights</b>                        | Good Working Condition |
| <b>Head lights - Dim</b>                   | Good Working Condition  | <b>Head lights - Bright</b>                     | Good Working Condition |
| <b>Fog Lights Front</b>                    | Good Working Condition  | <b>Rear Fog Lights</b>                          | Good Working Condition |
| <b>Rear Park Lights</b>                    | Good Working Condition  | <b>Daytime Driving Lights</b>                   | Good Working Condition |
| <b>Reverse Lights</b>                      | Good Working Condition  | <b>Stop Lights</b>                              | Good Working Condition |
| <b>Number Plate Light</b>                  | Good Working Condition  | <b>Hazard Lights</b>                            | Good Working Condition |
| <b>LHS Indicator</b>                       | Good Working Condition  | <b>RHS Indicator</b>                            | Good Working Condition |
| <b>Interior Lights</b>                     | Good Working Condition  | <b>Controls/Switches</b>                        | Good Working Condition |
| <b>Instruments</b>                         | Good Working Condition  | <b>Horn</b>                                     | Good Working Condition |
| <b>Driver Window Mechanism</b>             | Good Working Condition  | <b>Passenger Window Mechanism</b>               | Good Working Condition |
| <b>LHS Rear Window Mechanism</b>           | Good Working Condition  | <b>RHS Rear Window Mechanism</b>                | Good Working Condition |
| <b>Sunroof Operation</b>                   | N/A                     | <b>Convertible Roof</b>                         | N/A                    |
| <b>LHS Mirror Adjustment</b>               | Good Working Condition  | <b>RHS Mirror Adjustment</b>                    | Good Working Condition |
| <b>Rear Wiper and Washer</b>               | N/A                     | <b>Windscreen Wiper and Washer</b>              | Good Working Condition |
| <b>Air Conditioner / HVAC System</b>       | Good Working Condition  | <b>Radio and Audio System</b>                   | Good Working Condition |
| <b>Driver Seat – Seat Belt</b>             | Good Working Condition  |                                                 |                        |
| <b>Driver Seat – Adjustments</b>           | Good Working Condition  | <b>Driver Seat – Upholstery</b>                 | Good Working Condition |
| <b>Passenger Seat – Seat Belt</b>          | Good Working Condition  |                                                 |                        |
| <b>Passenger Seat – Upholstery</b>         | Good Working Condition  | <b>Passenger Seat – Adjustments</b>             | Good Working Condition |
| <b>Rear Passenger Seats – Seat Belt(s)</b> | Good Working Condition  |                                                 |                        |
| <b>Rear Passenger Seats – Upholstery</b>   | Good Working Condition  | <b>Rear Passenger Seats – Adjustments</b>       | Good Working Condition |
| <b>Panels, Covers and Trim Fitment</b>     | Good Working Condition  | <b>Diagnostic Fault Codes</b>                   | Good Working Condition |
| <b>Rear View Mirror</b>                    | Good Working Condition  | <b>Roof Lining Fitment</b>                      | Good Working Condition |
| <b>Cabin Heater</b>                        | Good Working Condition  | <b>Carpets and Mats</b>                         | Good Working Condition |
| <b>Set Clock</b>                           | Good Working Condition  | <b>Check &amp; Clear Diagnostic Fault Codes</b> | Good Working Condition |
| <b>Bonnet Release Lever</b>                | Good Working Condition  |                                                 |                        |
| <b>Comments</b>                            | Interior in great shape |                                                 |                        |

## BOOT

|                          |                        |                            |                                |
|--------------------------|------------------------|----------------------------|--------------------------------|
| <b>Boot lock</b>         | Good Working Condition | <b>Boot Hinges</b>         | Good Working Condition         |
| <b>Boot Linings</b>      | All correctly Fitted   | <b>Spare Wheel</b>         | More than 20% tread & inflated |
| <b>Jack</b>              | Present & Functioning  | <b>Wheel Spanner</b>       | Present & Functioning          |
| <b>Security Lock Nut</b> | Present & Functioning  | <b>Run Flat Repair Kit</b> | N/A                            |
| <b>Comments</b>          | Tools under rear seat  |                            |                                |

## UNDER CARRIAGE

|                                         |                        |                                        |                        |
|-----------------------------------------|------------------------|----------------------------------------|------------------------|
| Steering System Play                    | Good Working Condition | Oil and Fluid Leaks                    | Good Working Condition |
| Exhaust Leaks                           | Good Working Condition |                                        |                        |
| Shocks (leaks) Front                    | Good Working Condition | Shocks (leaks) Rear                    | Good Working Condition |
| Springs/Suspension Bushes & Links Front | Good Working Condition | Springs/Suspension Bushes & Links Rear | Good Working Condition |
| Front Brakes – Disc's & Pads            | Good Working Condition | Rear Brakes – Disc's & Pads            | N/A                    |
| Brake Pipe Fitment                      | Good Working Condition | Rear Brakes – Drums & Shoes            | Good Working Condition |
| Front Wheel Bearings                    | Good Working Condition | Rear Wheel Bearings                    | Good Working Condition |
| Fuel Tank Leaks                         | Good Working Condition | Fuel Pipe Fitment                      | Good Working Condition |
| RF Tyre Tread                           | More than 50%          | RF Tyre Size                           | Correct as per OEM     |
| LF Tyre Tread                           | More than 50%          | LF Tyre Size                           | Correct as per OEM     |
| LR Tyre Tread                           | More than 50%          | LR Tyre Size                           | Correct as per OEM     |
| RR Tyre Tread                           | More than 50%          | RR Tyre Size                           | Correct as per OEM     |
|                                         |                        | Drive Shafts                           | Good Working Condition |
| Comments                                | Undercarriage in order |                                        |                        |

## TEST DRIVE

|                                     |                        |                                 |                        |
|-------------------------------------|------------------------|---------------------------------|------------------------|
| Noise at Idle (Cold)                | Good Working Condition | Excessive fumes/Smoke at idle   | Good Working Condition |
| Final Drive Noise                   | Good Working Condition | Gearbox Noise                   | Good Working Condition |
| Engine Noise                        | Good Working Condition | Turbo/Super Charger Noise       | Good Working Condition |
| Clutch Operation                    | N/A                    | Auto Gearbox Operation          | Good Working Condition |
| Cruise Control/Adaptive             | Good Working Condition | Instrument Cluster Functions    | Good Working Condition |
| Warning Lights                      | Good Working Condition | Overheating                     | Good Working Condition |
| Engine Performance                  | Good Working Condition | Road holding / Stability        | Good Working Condition |
| Brake Operation                     | Good Working Condition | Brake Noise                     | Good Working Condition |
| Brake Shudder                       | No                     | Emergency Stop Test / ABS       | Good Working Condition |
| Steering Effort and Play            | Good Working Condition | Suspension Noise                | No                     |
| Vibrations & Harshness over 110km/h | No                     | Handbrake function              | Good Working Condition |
| Hot Restarting                      | Good Working Condition | Re-check Diagnostic Fault Codes | No Fault Codes         |
| Comments                            | Car drives great       |                                 |                        |

## GENERAL COMMENTS