

GENERAL

Report Name	Botha & Deysel workshop - KHG955EC
Client Name	Botha & Deysel workshop
Assessment Centre	Botha En Deysel Werkswinkel
Assessor	Hugo van Zyl
Inspection Date	30-12-2025 13:08:00


VEHICLE

Year	2022
Reg No	KHG955EC
Colour	White / Wit
VIN	MBHCZF63S00157177
Make	SUZUKI
Model	DZIRE 1.2 GL A/T
Current Odometer	91000
Engine	K12MP4264119

CHECKS & REPORTS

OEM Warranty Active	False	Warranty Details	N/A
Aftermarket Warranty Active	False	Type Of Warranty	N/A
Service History	All Service Intervals completed by OEM or Aftermarket	Service History Invoices Available	True
Accident Damage Disclosure	None	Major Repair Disclosure	None

BODY EXTERIOR

Number Plates	SABS Approved	Windscreens	No Cracks or Chips
Side Mirrors	No Damages or Paint Issues	Door Locks	Good Working Condition
Dents, Scratches and Misalignments	No Damages or paint issues		
Damage Mark Up		Comments	Exterior in great shape

STARTING AND CHARGING SYSTEM

Battery condition	Battery voltage normal 12.6 V
Battery Voltage Starting 9.6 V	Alternator Charging 13.5v - 15v
Comments	

ENGINE COMPARTMENT

Bonnet Hinge	Bonnet Catch
Coolant Level	Radiator Cap
Hoses / Pipes	Auxiliary Drive Belts
Brake Fluid level	Engine oil level and Condition
Power Steering Oil level	Clutch Fluid (if separate)
Oil & Fluid Leaks	All Components Secured Safely
Comments	

INTERIOR

Ignition Lock; switch	Front Park Lights
Head lights - Dim	Head lights - Bright
Fog Lights Front	Rear Fog Lights
Rear Park Lights	Daytime Driving Lights
Reverse Lights	Stop Lights
Number Plate Light	Hazard Lights
LHS Indicator	RHS Indicator
Interior Lights	Controls/Switches
Instruments	Horn
Driver Window Mechanism	Passenger Window Mechanism
LHS Rear Window Mechanism	RHS Rear Window Mechanism
Sunroof Operation	Convertible Roof
LHS Mirror Adjustment	RHS Mirror Adjustment
Rear Wiper and Washer	Windscreen Wiper and Washer
Air Conditioner / HVAC System	Radio and Audio System
Driver Seat – Seat Belt	
Driver Seat – Adjustments	Driver Seat – Upholstery
Passenger Seat – Seat Belt	
Passenger Seat – Upholstery	Passenger Seat – Adjustments
Rear Passenger Seats – Seat	
Belt(s)	
Rear Passenger Seats – Upholstery	Rear Passenger Seats – Adjustments
Panels, Covers and Trim Fitment	Diagnostic Fault Codes
Rear View Mirror	Roof Lining Fitment
Cabin Heater	Carpets and Mats
Set Clock	Check & Clear Diagnostic Fault Codes
Bonnet Release Lever	
Comments	

BOOT

Boot lock	Boot Hinges
Boot Linings	Spare Wheel
Jack	Wheel Spanner
Security Lock Nut	Run Flat Repair Kit
Comments	

UNDER CARRIAGE

Steering System Play	Oil and Fluid Leaks
Exhaust Leaks	
Shocks (leaks) Front	Shocks (leaks) Rear
Springs/Suspension Bushes & Links Front	Springs/Suspension Bushes & Links Rear
Front Brakes – Disc's & Pads	Rear Brakes – Disc's & Pads
Brake Pipe Fitment	Rear Brakes – Drums & Shoes
Front Wheel Bearings	Rear Wheel Bearings
Fuel Tank Leaks	Fuel Pipe Fitment
RF Tyre Tread	RF Tyre Size
LF Tyre Tread	LF Tyre Size
LR Tyre Tread	LR Tyre Size
RR Tyre Tread	RR Tyre Size
Comments	Drive Shafts

TEST DRIVE

Noise at Idle (Cold)		Excessive fumes/Smoke at idle	
Final Drive Noise		Gearbox Noise	
Engine Noise		Turbo/Super Charger Noise	
Clutch Operation	N/A	Auto Gearbox Operation	N/A
Cruise Control/Adaptive	N/A	Instrument Cluster Functions	Good Working Condition
Warning Lights	Good Working Condition	Overheating	Good Working Condition
Engine Performance	Good Working Condition	Road holding / Stability	Good Working Condition
Brake Operation	Good Working Condition	Brake Noise	Good Working Condition
Brake Shudder	No	Emergency Stop Test / ABS	Good Working Condition
Steering Effort and Play	Good Working Condition	Suspension Noise	No
Vibrations & Harshness over 110km/h	No	Handbrake function	Good Working Condition
Hot Restarting	Good Working Condition	Re-check Diagnostic Fault Codes	No Fault Codes
Comments	Car drives great		

GENERAL COMMENTS