

### GENERAL

Report Name	Botha & Deysel workshop - LS55WRGP
Client Name	Botha & Deysel workshop
Assessment Centre	Botha En Deysel Werkswinkel
Assessor	Hugo van Zyl
Inspection Date	09-02-2026 15:36:57




### VEHICLE

Year	2024
Reg No	LS55WRGP
Colour	Blue / Blou
VIN	KNADB514LP6805146
Make	KIA
Model	RIO 1.4 LS 5DR
Current Odometer	25787
Engine	G4LCPS134422

### CHECKS & REPORTS

OEM Warranty Active	True	Warranty Details	Yes
Aftermarket Warranty Active	False	Type Of Warranty	N/A
Service History	All Service Intervals completed by OEM or Aftermarket	Service History Invoices Available	True
Accident Damage Disclosure	None	Major Repair Disclosure	None

### BODY EXTERIOR

Number Plates	SABS Approved	Windscreens	No Cracks or Chips
Side Mirrors	No Damages or Paint Issues	Door Locks	Good Working Condition
Dents, Scratches and Misalignments	No Damages or paint issues	Wheel Nuts Torqued to OEM Spec	No; to be torqued
Damage Mark Up	    		
Comments	Comments		

### STARTING AND CHARGING SYSTEM

Battery condition	Good Working Condition	Battery voltage normal 12.6 V	Good Working Condition
Battery Voltage Starting 9.6 V	Good Working Condition	Alternator Charging 13.5v - 15v	Good Working Condition
Comments	Comments		

## ENGINE COMPARTMENT

<b>Bonnet Hinge</b>	Good Working Condition	<b>Bonnet Catch</b>	Good Working Condition
<b>Coolant Level</b>	Good Working Condition	<b>Radiator Cap</b>	Good Working Condition
<b>Hoses / Pipes</b>	All Functioning, No Leaks	<b>Auxiliary Drive Belts</b>	Good Working Condition
<b>Brake Fluid level</b>	Good Working Condition	<b>Engine oil level and Condition</b>	Good Working Condition
<b>Power Steering Oil level</b>	Good Working Condition	<b>Clutch Fluid (if separate)</b>	Good Working Condition
<b>Oil &amp; Fluid Leaks</b>	All Functioning, No Leaks	<b>All Components Secured Safely</b>	Good Working Condition
<b>Comments</b>	Engine compartment in order		

## INTERIOR

<b>Ignition Lock; switch</b>	Good Working Condition	<b>Front Park Lights</b>	Good Working Condition
<b>Head lights - Dim</b>	Good Working Condition	<b>Head lights - Bright</b>	Good Working Condition
<b>Fog Lights Front</b>	Good Working Condition	<b>Rear Fog Lights</b>	Good Working Condition
<b>Rear Park Lights</b>	Good Working Condition	<b>Daytime Driving Lights</b>	Good Working Condition
<b>Reverse Lights</b>	Good Working Condition	<b>Stop Lights</b>	Good Working Condition
<b>Number Plate Light</b>	Good Working Condition	<b>Hazard Lights</b>	Good Working Condition
<b>LHS Indicator</b>	Good Working Condition	<b>RHS Indicator</b>	Good Working Condition
<b>Interior Lights</b>	Good Working Condition	<b>Controls/Switches</b>	Good Working Condition
<b>Instruments</b>	Good Working Condition	<b>Horn</b>	Good Working Condition
<b>Driver Window Mechanism</b>	Good Working Condition	<b>Passenger Window Mechanism</b>	Good Working Condition
<b>LHS Rear Window Mechanism</b>	Good Working Condition	<b>RHS Rear Window Mechanism</b>	Good Working Condition
<b>Sunroof Operation</b>	N/A	<b>Convertible Roof</b>	N/A
<b>LHS Mirror Adjustment</b>	Good Working Condition	<b>RHS Mirror Adjustment</b>	Good Working Condition
<b>Rear Wiper and Washer</b>	Good Working Condition	<b>Windscreen Wiper and Washer</b>	Good Working Condition
<b>Air Conditioner / HVAC System</b>	Good Working Condition	<b>Radio and Audio System</b>	Good Working Condition
<b>Driver Seat – Seat Belt</b>	Good Working Condition		
<b>Driver Seat – Adjustments</b>	Good Working Condition	<b>Driver Seat – Upholstery</b>	Good Working Condition
<b>Passenger Seat – Seat Belt</b>	Good Working Condition		
<b>Passenger Seat – Upholstery</b>	Good Working Condition	<b>Passenger Seat – Adjustments</b>	Good Working Condition
<b>Rear Passenger Seats – Seat Belt(s)</b>	Good Working Condition		
<b>Rear Passenger Seats – Upholstery</b>	Good Working Condition	<b>Rear Passenger Seats – Adjustments</b>	Good Working Condition
<b>Panels, Covers and Trim Fitment</b>	Good Working Condition	<b>Diagnostic Fault Codes</b>	Good Working Condition
<b>Rear View Mirror</b>	Good Working Condition	<b>Roof Lining Fitment</b>	Good Working Condition
<b>Cabin Heater</b>	Good Working Condition	<b>Carpets and Mats</b>	Good Working Condition
<b>Set Clock</b>	Good Working Condition	<b>Check &amp; Clear Diagnostic Fault Codes</b>	Good Working Condition
<b>Bonnet Release Lever</b>	Good Working Condition		
<b>Comments</b>	Interior in great shape		

## BOOT

<b>Boot lock</b>	Good Working Condition	<b>Boot Hinges</b>	Good Working Condition
<b>Boot Linings</b>	All correctly Fitted	<b>Spare Wheel</b>	More than 20% tread & inflated
<b>Jack</b>	Present & Functioning	<b>Wheel Spanner</b>	Present & Functioning
<b>Security Lock Nut</b>	N/A	<b>Run Flat Repair Kit</b>	N/A
<b>Comments</b>	Boot in order		

## UNDER CARRIAGE

Steering System Play	Good Working Condition	Oil and Fluid Leaks	Good Working Condition
Exhaust Leaks	Good Working Condition		
Shocks (leaks) Front	Good Working Condition	Shocks (leaks) Rear	Good Working Condition
Springs/Suspension Bushes & Links Front	Good Working Condition	Springs/Suspension Bushes & Links Rear	Good Working Condition
Front Brakes – Disc's & Pads	Good Working Condition	Rear Brakes – Disc's & Pads	N/A
Brake Pipe Fitment	Good Working Condition	Rear Brakes – Drums & Shoes	Good Working Condition
Front Wheel Bearings	Good Working Condition	Rear Wheel Bearings	Good Working Condition
Fuel Tank Leaks	Good Working Condition	Fuel Pipe Fitment	Good Working Condition
RF Tyre Tread	More than 50%	RF Tyre Size	Correct as per OEM
LF Tyre Tread	More than 50%	LF Tyre Size	Correct as per OEM
LR Tyre Tread	More than 50%	LR Tyre Size	Correct as per OEM
RR Tyre Tread	More than 50%	RR Tyre Size	Correct as per OEM
		Drive Shafts	Good Working Condition
Comments	Undercarriage in order		

## TEST DRIVE

Noise at Idle (Cold)	Good Working Condition	Excessive fumes/Smoke at idle	Good Working Condition
Final Drive Noise	Good Working Condition	Gearbox Noise	Good Working Condition
Engine Noise	Good Working Condition	Turbo/Super Charger Noise	N/A
Clutch Operation	Good Working Condition	Auto Gearbox Operation	N/A
Cruise Control/Adaptive	N/A	Instrument Cluster Functions	Good Working Condition
Warning Lights	Good Working Condition	Overheating	Good Working Condition
Engine Performance	Good Working Condition	Road holding / Stability	Good Working Condition
Brake Operation	Good Working Condition	Brake Noise	Good Working Condition
Brake Shudder	No	Emergency Stop Test / ABS	Good Working Condition
Steering Effort and Play	Good Working Condition	Suspension Noise	No
Vibrations & Harshness over 110km/h	No	Handbrake function	Good Working Condition
Hot Restarting	Good Working Condition	Re-check Diagnostic Fault Codes	No Fault Codes
Comments	Car drives great		

## GENERAL COMMENTS