

**GENERAL**

Report Name	Botha & Deysel workshop - CK53970
Client Name	Botha & Deysel workshop
Assessment Centre	Botha En Deysel Werkswinkel
Assessor	Hugo van Zyl
Inspection Date	15-04-2026 11:28:32

**VEHICLE**


Year	2017
Reg No	CK53970
Colour	White / Wit
VIN	AFAGXXMJ2GHA03487
Make	FORD
Model	RANGER 2.2TDCI XL A/T P/U S/C
Current Odometer	193000
Engine	QJ2LGHA03487

**CHECKS & REPORTS**

OEM Warranty Active	False	Warranty Details	N/A
Aftermarket Warranty Active	False	Type Of Warranty	N/A
Service History	All Service Intervals completed by OEM or Aftermarket	Service History Invoices Available	True
Accident Damage Disclosure	None	Major Repair Disclosure	None

**BODY EXTERIOR**

Number Plates	SABS Approved	Windscreen	No Cracks or Chips
Side Mirrors	No Damages or Paint Issues	Door Locks	Good Working Condition
Dents, Scratches and Misalignments	No Damages or paint issues	Wheel Nuts Torqued to OEM Spec	Yes; Torqued to Spec



Comments

Exterior in order

## **STARTING AND CHARGING SYSTEM**

<b>Battery condition</b>	Good Working Condition	<b>Battery voltage normal 12.6 V</b>	Good Working Condition
<b>Battery Voltage Starting 9.6 V</b>	Good Working Condition	<b>Alternator Charging 13.5v - 15v</b>	Good Working Condition
<b>Comments</b>	Starting system in order		

## **ENGINE COMPARTMENT**

<b>Bonnet Hinge</b>	Good Working Condition	<b>Bonnet Catch</b>	Good Working Condition
<b>Coolant Level</b>	Good Working Condition	<b>Radiator Cap</b>	Good Working Condition
<b>Hoses / Pipes</b>	All Functioning, No Leaks	<b>Auxiliary Drive Belts</b>	Good Working Condition
<b>Brake Fluid level</b>	Good Working Condition	<b>Engine oil level and Condition</b>	Good Working Condition
<b>Power Steering Oil level</b>	Good Working Condition	<b>Clutch Fluid (if separate)</b>	N/A
<b>Oil &amp; Fluid Leaks</b>	All Functioning, No Leaks	<b>All Components Secured Safely</b>	Good Working Condition
<b>Comments</b>	Engine compartment in order		

## **INTERIOR**

<b>Ignition Lock; switch</b>	Good Working Condition	<b>Front Park Lights</b>	Good Working Condition
<b>Head lights - Dim</b>	Good Working Condition	<b>Head lights - Bright</b>	Good Working Condition
<b>Fog Lights Front</b>	N/A	<b>Rear Fog Lights</b>	N/A
<b>Rear Park Lights</b>	Good Working Condition	<b>Daytime Driving Lights</b>	N/A
<b>Reverse Lights</b>	Good Working Condition	<b>Stop Lights</b>	Good Working Condition
<b>Number Plate Light</b>	Good Working Condition	<b>Hazard Lights</b>	Good Working Condition
<b>LHS Indicator</b>	Good Working Condition	<b>RHS Indicator</b>	Good Working Condition
<b>Interior Lights</b>	Good Working Condition	<b>Controls/Switches</b>	Good Working Condition
<b>Instruments</b>	Good Working Condition	<b>Horn</b>	Good Working Condition
<b>Driver Window Mechanism</b>	Good Working Condition	<b>Passenger Window Mechanism</b>	Good Working Condition
<b>LHS Rear Window Mechanism</b>	N/A	<b>RHS Rear Window Mechanism</b>	N/A
<b>Sunroof Operation</b>	N/A	<b>Convertible Roof</b>	N/A
<b>LHS Mirror Adjustment</b>	Good Working Condition	<b>RHS Mirror Adjustment</b>	Good Working Condition
<b>Rear Wiper and Washer</b>	N/A	<b>Windscreen Wiper and Washer</b>	Good Working Condition
<b>Air Conditioner / HVAC System</b>	Good Working Condition	<b>Radio and Audio System</b>	Good Working Condition
<b>Driver Seat – Seat Belt</b>	Good Working Condition		
<b>Driver Seat – Adjustments</b>	Good Working Condition	<b>Driver Seat – Upholstery</b>	Good Working Condition
<b>Passenger Seat – Seat Belt</b>	Good Working Condition		
<b>Passenger Seat – Upholstery</b>	Good Working Condition	<b>Passenger Seat – Adjustments</b>	Good Working Condition
<b>Rear Passenger Seats – Seat Belt(s)</b>	Good Working Condition		
<b>Rear Passenger Seats – Upholstery</b>	Good Working Condition	<b>Rear Passenger Seats – Adjustments</b>	Good Working Condition
<b>Panels, Covers and Trim Fitment</b>	Good Working Condition	<b>Diagnostic Fault Codes</b>	Good Working Condition
<b>Rear View Mirror</b>	Good Working Condition	<b>Roof Lining Fitment</b>	Good Working Condition
<b>Cabin Heater</b>	Good Working Condition	<b>Carpets and Mats</b>	Good Working Condition
<b>Set Clock</b>	Good Working Condition	<b>Check &amp; Clear Diagnostic Fault Codes</b>	Good Working Condition
<b>Bonnet Release Lever</b>	Good Working Condition		
<b>Comments</b>	Interior in great condition		

## BOOT

Boot lock	Good Working Condition	Boot Hinges	Good Working Condition
Boot Linings	All correctly Fitted	Spare Wheel	More than 20% tread & inflated
Jack	Present & Functioning	Wheel Spanner	Present & Functioning
Security Lock Nut	N/A	Run Flat Repair Kit	N/A
Comments	Tools in order		

## UNDER CARRIAGE

Steering System Play	Good Working Condition	Oil and Fluid Leaks	Good Working Condition
Exhaust Leaks	Good Working Condition		
Shocks (leaks) Front	Good Working Condition	Shocks (leaks) Rear	Good Working Condition
Springs/Suspension Bushes & Links Front	Good Working Condition	Springs/Suspension Bushes & Links Rear	Good Working Condition
Front Brakes – Disc's & Pads	Good Working Condition	Rear Brakes – Disc's & Pads	N/A
Brake Pipe Fitment	Good Working Condition	Rear Brakes – Drums & Shoes	Good Working Condition
Front Wheel Bearings	Good Working Condition	Rear Wheel Bearings	Good Working Condition
Fuel Tank Leaks	Good Working Condition	Fuel Pipe Fitment	Good Working Condition
RF Tyre Tread	More than 50%	RF Tyre Size	Correct as per OEM
LF Tyre Tread	More than 50%	LF Tyre Size	Correct as per OEM
LR Tyre Tread	More than 50%	LR Tyre Size	Correct as per OEM
RR Tyre Tread	More than 50%	RR Tyre Size	Correct as per OEM
		Drive Shafts	Good Working Condition
Comments	Undercarriage in order		

## TEST DRIVE

Noise at Idle (Cold)	Good Working Condition	Excessive fumes/Smoke at idle	Good Working Condition
Final Drive Noise	Good Working Condition	Gearbox Noise	Good Working Condition
Engine Noise	Good Working Condition	Turbo/Super Charger Noise	Good Working Condition
Clutch Operation	N/A	Auto Gearbox Operation	Good Working Condition
Cruise Control/Adaptive	N/A	Instrument Cluster Functions	Good Working Condition
Warning Lights	Good Working Condition	Overheating	Good Working Condition
Engine Performance	Good Working Condition	Road holding / Stability	Good Working Condition
Brake Operation	Good Working Condition	Brake Noise	Good Working Condition
Brake Shudder	No	Emergency Stop Test / ABS	Good Working Condition
Steering Effort and Play	Good Working Condition	Suspension Noise	No
Vibrations & Harshness over 110km/h	No	Handbrake function	Good Working Condition
Hot Restarting	Good Working Condition	Re-check Diagnostic Fault Codes	No Fault Codes
Comments	Bakkie drives great		

## GENERAL COMMENTS