

**GENERAL**

Report Name	Botha & Deysel workshop - LT46RCGP
Client Name	Botha & Deysel workshop
Assessment Centre	Botha En Deysel Werkswinkel
Assessor	Hugo van Zyl
Inspection Date	12-05-2026 12:08:16

**VEHICLE**


Year	2008
Reg No	LT46RCGP
Colour	White / Wit
VIN	JTEEB71J307002750
Make	TOYOTA
Model	LANDCRUISER 70 4.2D S/W
Current Odometer	127000
Engine	1HZ0583493

**CHECKS & REPORTS**

OEM Warranty Active	False	Warranty Details	N/A
Aftermarket Warranty Active	False	Type Of Warranty	N/A
Service History	Not all service intervals completed	Service History Invoices Available	True
Accident Damage Disclosure	None	Major Repair Disclosure	None

**BODY EXTERIOR**

Number Plates	SABS Approved	Windscreen	Minor Chips
Side Mirrors	No Damages or Paint Issues	Door Locks	Good Working Condition
Dents, Scratches and Misalignments	Minor damages or paint issues	Wheel Nuts Torqued to OEM Spec	Yes; Torqued to Spec

<p>Damage Mark Up</p>		<p>Comments</p> <p>Exterior in order</p>
-----------------------	---	--

**STARTING AND CHARGING SYSTEM**

Battery condition	Good Working Condition	Battery voltage normal 12.6 V	Good Working Condition
Battery Voltage Starting 9.6 V	Good Working Condition	Alternator Charging 13.5v - 15v	Good Working Condition
Comments	Starting system in order		

## ENGINE COMPARTMENT

Bonnet Hinge	Good Working Condition	Bonnet Catch	Good Working Condition
Coolant Level	Good Working Condition	Radiator Cap	Good Working Condition
Hoses / Pipes	All Functioning, No Leaks	Auxiliary Drive Belts	Good Working Condition
Brake Fluid level	Good Working Condition	Engine oil level and Condition	Good Working Condition
Power Steering Oil level	Good Working Condition	Clutch Fluid (if separate)	Good Working Condition
Oil & Fluid Leaks	All Functioning, No Leaks	All Components Secured Safely	Good Working Condition
Comments	Engine compartment in order		

## INTERIOR

Ignition Lock; switch	Good Working Condition	Front Park Lights	Good Working Condition
Head lights - Dim	Good Working Condition	Head lights - Bright	Good Working Condition
Fog Lights Front	Good Working Condition	Rear Fog Lights	Good Working Condition
Rear Park Lights	Good Working Condition	Daytime Driving Lights	N/A
Reverse Lights	Good Working Condition	Stop Lights	Good Working Condition
Number Plate Light	Good Working Condition	Hazard Lights	Good Working Condition
LHS Indicator	Good Working Condition	RHS Indicator	Good Working Condition
Interior Lights	Good Working Condition	Controls/Switches	Good Working Condition
Instruments	Good Working Condition	Horn	Good Working Condition
Driver Window Mechanism	Good Working Condition	Passenger Window Mechanism	Good Working Condition
LHS Rear Window Mechanism	Good Working Condition	RHS Rear Window Mechanism	Good Working Condition
Sunroof Operation	N/A	Convertible Roof	N/A
LHS Mirror Adjustment	Good Working Condition	RHS Mirror Adjustment	Good Working Condition
Rear Wiper and Washer	Good Working Condition	Windscreen Wiper and Washer	Good Working Condition
Air Conditioner / HVAC System	Good Working Condition	Radio and Audio System	Good Working Condition
Driver Seat – Seat Belt	Good Working Condition		
Driver Seat – Adjustments	Good Working Condition	Driver Seat – Upholstery	Good Working Condition
Passenger Seat – Seat Belt	Good Working Condition		
Passenger Seat – Upholstery	Good Working Condition	Passenger Seat – Adjustments	Good Working Condition
Rear Passenger Seats – Seat Belt(s)	Good Working Condition		
Rear Passenger Seats – Upholstery	Good Working Condition	Rear Passenger Seats – Adjustments	Good Working Condition
Panels, Covers and Trim Fitment	Good Working Condition	Diagnostic Fault Codes	Good Working Condition
Rear View Mirror	Good Working Condition	Roof Lining Fitment	Good Working Condition
Cabin Heater	Good Working Condition	Carpets and Mats	Good Working Condition
Set Clock	Good Working Condition	Check & Clear Diagnostic Fault Codes	Good Working Condition
Bonnet Release Lever	Good Working Condition		
Comments	Interior in great condition		

## BOOT

Boot lock	Good Working Condition	Boot Hinges	Good Working Condition
Boot Linings	All correctly Fitted	Spare Wheel	More than 20% tread & inflated
Jack	Present & Functioning	Wheel Spanner	Present & Functioning
Security Lock Nut	N/A	Run Flat Repair Kit	N/A
Comments	Boot in order		

## UNDER CARRIAGE

<b>Steering System Play</b>	Good Working Condition	<b>Oil and Fluid Leaks</b>	Good Working Condition
<b>Exhaust Leaks</b>	Good Working Condition		
<b>Shocks (leaks) Front</b>	Good Working Condition	<b>Shocks (leaks) Rear</b>	Good Working Condition
<b>Springs/Suspension Bushes &amp; Links Front</b>	Good Working Condition	<b>Springs/Suspension Bushes &amp; Links Rear</b>	Good Working Condition
<b>Front Brakes – Disc's &amp; Pads</b>	Good Working Condition	<b>Rear Brakes – Disc's &amp; Pads</b>	N/A
<b>Brake Pipe Fitment</b>	Good Working Condition	<b>Rear Brakes – Drums &amp; Shoes</b>	Good Working Condition
<b>Front Wheel Bearings</b>	Good Working Condition	<b>Rear Wheel Bearings</b>	Good Working Condition
<b>Fuel Tank Leaks</b>	Good Working Condition	<b>Fuel Pipe Fitment</b>	Good Working Condition
<b>RF Tyre Tread</b>	More than 25%	<b>RF Tyre Size</b>	Correct as per OEM
<b>LF Tyre Tread</b>	Worn beyond wear limit	<b>LF Tyre Size</b>	Correct as per OEM
<b>LR Tyre Tread</b>	More than 25%	<b>LR Tyre Size</b>	Correct as per OEM
<b>RR Tyre Tread</b>	More than 25%	<b>RR Tyre Size</b>	Correct as per OEM
		<b>Drive Shafts</b>	Good Working Condition
<b>Comments</b>	Undercarriage in order		

## TEST DRIVE

<b>Noise at Idle (Cold)</b>	Good Working Condition	<b>Excessive fumes/Smoke at idle</b>	Good Working Condition
<b>Final Drive Noise</b>	Good Working Condition	<b>Gearbox Noise</b>	Good Working Condition
<b>Engine Noise</b>	Good Working Condition	<b>Turbo/Super Charger Noise</b>	N/A
<b>Clutch Operation</b>	Good Working Condition	<b>Auto Gearbox Operation</b>	N/A
<b>Cruise Control/Adaptive</b>	N/A	<b>Instrument Cluster Functions</b>	Good Working Condition
<b>Warning Lights</b>	Good Working Condition	<b>Overheating</b>	Good Working Condition
<b>Engine Performance</b>	Good Working Condition	<b>Road holding / Stability</b>	Good Working Condition
<b>Brake Operation</b>	Good Working Condition	<b>Brake Noise</b>	Good Working Condition
<b>Brake Shudder</b>	No	<b>Emergency Stop Test / ABS</b>	Good Working Condition
<b>Steering Effort and Play</b>	Good Working Condition	<b>Suspension Noise</b>	No
<b>Vibrations &amp; Harshness over 110km/h</b>	No	<b>Handbrake function</b>	Good Working Condition
<b>Hot Restarting</b>	Good Working Condition	<b>Re-check Diagnostic Fault Codes</b>	No Fault Codes
<b>Comments</b>	Car drives great		

## GENERAL COMMENTS