

**GENERAL**

|                   |                                |
|-------------------|--------------------------------|
| Report Name       | Botha & Deysel - HVL569FS      |
| Client Name       | Botha & Deysel                 |
| Assessment Centre | Botha En Deysel<br>Werkswinkel |
| Assessor          | Hugo van Zyl                   |
| Inspection Date   | 14-05-2026 12:10:56            |

**VEHICLE**

|                  |                             |
|------------------|-----------------------------|
| Year             | 2017                        |
| Reg No           | HVL569FS                    |
| Colour           | White / Wit                 |
| VIN              | AHTCB8GS802205795           |
| Make             | TOYOTA                      |
| Model            | FORTUNER 2.4GD-6 R/B<br>A/T |
| Current Odometer | 132000                      |
| Engine           | 2GD0310036                  |


**CHECKS & REPORTS**

|                             |   |                                    |       |
|-----------------------------|---|------------------------------------|-------|
| OEM Warranty Active         | False   | Warranty Details                   | N/A   |
| Aftermarket Warranty Active | False   | Type Of Warranty                   | N/A   |
| Service History             | All Service Intervals completed by OEM or Aftermarket | Service History Invoices Available | False |
| Accident Damage Disclosure  | None  | Major Repair Disclosure            | None  |

**BODY EXTERIOR**

|                                    |                            |                                |                        |
|------------------------------------|----------------------------|--------------------------------|------------------------|
| Number Plates                      | SABS Approved              | Windscreen                     | No Cracks or Chips     |
| Side Mirrors                       | No Damages or Paint Issues | Door Locks                     | Good Working Condition |
| Dents, Scratches and Misalignments | No Damages or paint issues | Wheel Nuts Torqued to OEM Spec | Yes; Torqued to Spec   |

Damage Mark Up



|          |                   |
|----------|-------------------|
| Comments | Exterior in order |
|----------|-------------------|

## **STARTING AND CHARGING SYSTEM**

|                                |                          |                                 |                        |
|--------------------------------|--------------------------|---------------------------------|------------------------|
| Battery condition              | Good Working Condition   | Battery voltage normal 12.6 V   | Good Working Condition |
| Battery Voltage Starting 9.6 V | Good Working Condition   | Alternator Charging 13.5v - 15v | Good Working Condition |
| Comments                       | Starting system in order |                                 |                        |

## **ENGINE COMPARTMENT**

|                          |                             |                                |                        |
|--------------------------|-----------------------------|--------------------------------|------------------------|
| Bonnet Hinge             | Good Working Condition      | Bonnet Catch                   | Good Working Condition |
| Coolant Level            | Good Working Condition      | Radiator Cap                   | Good Working Condition |
| Hoses / Pipes            | All Functioning, No Leaks   | Auxiliary Drive Belts          | Good Working Condition |
| Brake Fluid level        | Good Working Condition      | Engine oil level and Condition | Good Working Condition |
| Power Steering Oil level | Good Working Condition      | Clutch Fluid (if separate)     | N/A                    |
| Oil & Fluid Leaks        | All Functioning, No Leaks   | All Components Secured Safely  | Good Working Condition |
| Comments                 | Engine compartment in order |                                |                        |

## **INTERIOR**

|                                     |                             |                                      |                        |
|-------------------------------------|-----------------------------|--------------------------------------|------------------------|
| Ignition Lock; switch               | Good Working Condition      | Front Park Lights                    | Good Working Condition |
| Head lights - Dim                   | Good Working Condition      | Head lights - Bright                 | Good Working Condition |
| Fog Lights Front                    | Good Working Condition      | Rear Fog Lights                      | Good Working Condition |
| Rear Park Lights                    | Good Working Condition      | Daytime Driving Lights               | Good Working Condition |
| Reverse Lights                      | Good Working Condition      | Stop Lights                          | Good Working Condition |
| Number Plate Light                  | Good Working Condition      | Hazard Lights                        | Good Working Condition |
| LHS Indicator                       | Good Working Condition      | RHS Indicator                        | Good Working Condition |
| Interior Lights                     | Good Working Condition      | Controls/Switches                    | Good Working Condition |
| Instruments                         | Good Working Condition      | Horn                                 | Good Working Condition |
| Driver Window Mechanism             | Good Working Condition      | Passenger Window Mechanism           | Good Working Condition |
| LHS Rear Window Mechanism           | Good Working Condition      | RHS Rear Window Mechanism            | Good Working Condition |
| Sunroof Operation                   | N/A                         | Convertible Roof                     | N/A                    |
| LHS Mirror Adjustment               | Good Working Condition      | RHS Mirror Adjustment                | Good Working Condition |
| Rear Wiper and Washer               | Good Working Condition      | Windscreen Wiper and Washer          | Good Working Condition |
| Air Conditioner / HVAC System       | Good Working Condition      | Radio and Audio System               | Good Working Condition |
| Driver Seat – Seat Belt             | Good Working Condition      |                                      |                        |
| Driver Seat – Adjustments           | Good Working Condition      | Driver Seat – Upholstery             | Good Working Condition |
| Passenger Seat – Seat Belt          | Good Working Condition      |                                      |                        |
| Passenger Seat – Upholstery         | Good Working Condition      | Passenger Seat – Adjustments         | Good Working Condition |
| Rear Passenger Seats – Seat Belt(s) | Good Working Condition      |                                      |                        |
| Rear Passenger Seats – Upholstery   | Good Working Condition      | Rear Passenger Seats – Adjustments   | Good Working Condition |
| Panels, Covers and Trim Fitment     | Good Working Condition      | Diagnostic Fault Codes               | Good Working Condition |
| Rear View Mirror                    | Good Working Condition      | Roof Lining Fitment                  | Good Working Condition |
| Cabin Heater                        | Good Working Condition      | Carpets and Mats                     | Good Working Condition |
| Set Clock                           | Good Working Condition      | Check & Clear Diagnostic Fault Codes | Good Working Condition |
| Bonnet Release Lever                | Good Working Condition      |                                      |                        |
| Comments                            | Interior in great condition |                                      |                        |

## **BOOT**

|                          |                        |                            |                                |
|--------------------------|------------------------|----------------------------|--------------------------------|
| <b>Boot lock</b>         | Good Working Condition | <b>Boot Hinges</b>         | Good Working Condition         |
| <b>Boot Linings</b>      | All correctly Fitted   | <b>Spare Wheel</b>         | More than 20% tread & inflated |
| <b>Jack</b>              | Present & Functioning  | <b>Wheel Spanner</b>       | Present & Functioning          |
| <b>Security Lock Nut</b> | N/A                    | <b>Run Flat Repair Kit</b> | N/A                            |
| <b>Comments</b>          | Boot in order          |                            |                                |

## **UNDER CARRIAGE**

|  |                        |   |                        |
|--|------------------------|---|------------------------|
| <b>Steering System Play</b>                        | Good Working Condition | <b>Oil and Fluid Leaks</b>                        | Good Working Condition |
| <b>Exhaust Leaks</b>                               | Good Working Condition |   |                        |
| <b>Shocks (leaks) Front</b>                        | Good Working Condition | <b>Shocks (leaks) Rear</b>                        | Good Working Condition |
| <b>Springs/Suspension Bushes &amp; Links Front</b> | Good Working Condition | <b>Springs/Suspension Bushes &amp; Links Rear</b> | Good Working Condition |
| <b>Front Brakes – Disc's &amp; Pads</b>            | Good Working Condition | <b>Rear Brakes – Disc's &amp; Pads</b>            | N/A                    |
| <b>Brake Pipe Fitment</b>                          | Good Working Condition | <b>Rear Brakes – Drums &amp; Shoes</b>            | Good Working Condition |
| <b>Front Wheel Bearings</b>                        | Good Working Condition | <b>Rear Wheel Bearings</b>                        | Good Working Condition |
| <b>Fuel Tank Leaks</b>                             | Good Working Condition | <b>Fuel Pipe Fitment</b>                          | Good Working Condition |
| <b>RF Tyre Tread</b>                               | More than 50%          | <b>RF Tyre Size</b>                               | Correct as per OEM     |
| <b>LF Tyre Tread</b>                               | More than 50%          | <b>LF Tyre Size</b>                               | Correct as per OEM     |
| <b>LR Tyre Tread</b>                               | More than 50%          | <b>LR Tyre Size</b>                               | Correct as per OEM     |
| <b>RR Tyre Tread</b>                               | More than 50%          | <b>RR Tyre Size</b>                               | Correct as per OEM     |
|  |                        | <b>Drive Shafts</b>                               | Good Working Condition |
| <b>Comments</b>                                    | Undercarriage in order |   |                        |

## **TEST DRIVE**

|  |                        |  |                        |
|--|------------------------|--|------------------------|
| <b>Noise at Idle (Cold)</b>                    | Good Working Condition | <b>Excessive fumes/Smoke at idle</b>   | Good Working Condition |
| <b>Final Drive Noise</b>                       | Good Working Condition | <b>Gearbox Noise</b>                   | Good Working Condition |
| <b>Engine Noise</b>                            | Good Working Condition | <b>Turbo/Super Charger Noise</b>       | Good Working Condition |
| <b>Clutch Operation</b>                        | N/A                    | <b>Auto Gearbox Operation</b>          | Good Working Condition |
| <b>Cruise Control/Adaptive</b>                 | Good Working Condition | <b>Instrument Cluster Functions</b>    | Good Working Condition |
| <b>Warning Lights</b>                          | Good Working Condition | <b>Overheating</b>                     | Good Working Condition |
| <b>Engine Performance</b>                      | Good Working Condition | <b>Road holding / Stability</b>        | Good Working Condition |
| <b>Brake Operation</b>                         | Good Working Condition | <b>Brake Noise</b>                     | Good Working Condition |
| <b>Brake Shudder</b>                           | No                     | <b>Emergency Stop Test / ABS</b>       | Good Working Condition |
| <b>Steering Effort and Play</b>                | Good Working Condition | <b>Suspension Noise</b>                | No                     |
| <b>Vibrations &amp; Harshness over 110km/h</b> | No                     | <b>Handbrake function</b>              | Good Working Condition |
| <b>Hot Restarting</b>                          | Good Working Condition | <b>Re-check Diagnostic Fault Codes</b> | No Fault Codes         |
| <b>Comments</b>                                | Car drives great       |  |                        |

## **GENERAL COMMENTS**