

**GENERAL**

Report Name	Botha & Deysel workshop - MB49PFGP
Client Name	Botha & Deysel workshop
Assessment Centre	Botha En Deysel Werkswinkel
Assessor	Hugo van Zyl
Inspection Date	19-05-2026 14:53:07

**VEHICLE**


Year	2017
Reg No	MB49PFGP
Colour	White / Wit
VIN	KNAB2511MJT155920
Make	KIA
Model	PICANTO 1.0 STYLE A/T
Current Odometer	152000
Engine	G3LAHP142962

**CHECKS & REPORTS**

OEM Warranty Active	False	Warranty Details	N/A
Aftermarket Warranty Active	False	Type Of Warranty	N/A
Service History	All Service Intervals completed by OEM or Aftermarket	Service History Invoices Available	True
Accident Damage Disclosure	No	Major Repair Disclosure	No

**BODY EXTERIOR**

Number Plates	SABS Approved	Windscreen	Minor Chips
Side Mirrors	No Damages or Paint Issues	Door Locks	Good Working Condition
Dents, Scratches and Misalignments	No Damages or paint issues	Wheel Nuts Torqued to OEM Spec	Yes; Torqued to Spec



Comments	Exterior in order
----------	-------------------

**STARTING AND CHARGING SYSTEM**

Battery condition	Good Working Condition	Battery voltage normal 12.6 V	Good Working Condition
Battery Voltage Starting 9.6 V	Good Working Condition	Alternator Charging 13.5v - 15v	Good Working Condition
Comments	Starting system in order		

## ENGINE COMPARTMENT

<b>Bonnet Hinge</b>	Good Working Condition	<b>Bonnet Catch</b>	Good Working Condition
<b>Coolant Level</b>	Good Working Condition	<b>Radiator Cap</b>	Good Working Condition
<b>Hoses / Pipes</b>	All Functioning, No Leaks	<b>Auxiliary Drive Belts</b>	Good Working Condition
<b>Brake Fluid level</b>	Good Working Condition	<b>Engine oil level and Condition</b>	Good Working Condition
<b>Power Steering Oil level</b>	Good Working Condition	<b>Clutch Fluid (if separate)</b>	N/A
<b>Oil &amp; Fluid Leaks</b>	All Functioning, No Leaks	<b>All Components Secured Safely</b>	Good Working Condition
<b>Comments</b>	Engine compartment in order		

## INTERIOR

<b>Ignition Lock; switch</b>	Good Working Condition	<b>Front Park Lights</b>	Good Working Condition
<b>Head lights - Dim</b>	Good Working Condition	<b>Head lights - Bright</b>	Good Working Condition
<b>Fog Lights Front</b>	Good Working Condition	<b>Rear Fog Lights</b>	Good Working Condition
<b>Rear Park Lights</b>	Good Working Condition	<b>Daytime Driving Lights</b>	Good Working Condition
<b>Reverse Lights</b>	Good Working Condition	<b>Stop Lights</b>	Good Working Condition
<b>Number Plate Light</b>	Good Working Condition	<b>Hazard Lights</b>	Good Working Condition
<b>LHS Indicator</b>	Good Working Condition	<b>RHS Indicator</b>	Good Working Condition
<b>Interior Lights</b>	Good Working Condition	<b>Controls/Switches</b>	Good Working Condition
<b>Instruments</b>	Good Working Condition	<b>Horn</b>	Good Working Condition
<b>Driver Window Mechanism</b>	Good Working Condition	<b>Passenger Window Mechanism</b>	Good Working Condition
<b>LHS Rear Window Mechanism</b>	Good Working Condition	<b>RHS Rear Window Mechanism</b>	Good Working Condition
<b>Sunroof Operation</b>	N/A	<b>Convertible Roof</b>	N/A
<b>LHS Mirror Adjustment</b>	Good Working Condition	<b>RHS Mirror Adjustment</b>	Good Working Condition
<b>Rear Wiper and Washer</b>	Good Working Condition	<b>Windscreen Wiper and Washer</b>	Good Working Condition
<b>Air Conditioner / HVAC System</b>	Good Working Condition	<b>Radio and Audio System</b>	Good Working Condition
<b>Driver Seat – Seat Belt</b>	Good Working Condition		
<b>Driver Seat – Adjustments</b>	Good Working Condition	<b>Driver Seat – Upholstery</b>	Good Working Condition
<b>Passenger Seat – Seat Belt</b>	Good Working Condition		
<b>Passenger Seat – Upholstery</b>	Good Working Condition	<b>Passenger Seat – Adjustments</b>	Good Working Condition
<b>Rear Passenger Seats – Seat Belt(s)</b>	Good Working Condition		
<b>Rear Passenger Seats – Upholstery</b>	Good Working Condition	<b>Rear Passenger Seats – Adjustments</b>	Good Working Condition
<b>Panels, Covers and Trim Fitment</b>	Good Working Condition	<b>Diagnostic Fault Codes</b>	Good Working Condition
<b>Rear View Mirror</b>	Good Working Condition	<b>Roof Lining Fitment</b>	Good Working Condition
<b>Cabin Heater</b>	Good Working Condition	<b>Carpets and Mats</b>	Good Working Condition
<b>Set Clock</b>	Good Working Condition	<b>Check &amp; Clear Diagnostic Fault Codes</b>	Good Working Condition
<b>Bonnet Release Lever</b>	Good Working Condition		
<b>Comments</b>	Interior in great condition		

## BOOT

<b>Boot lock</b>	Good Working Condition	<b>Boot Hinges</b>	Good Working Condition
<b>Boot Linings</b>	All correctly Fitted	<b>Spare Wheel</b>	More than 20% tread & inflated
<b>Jack</b>	Present & Functioning	<b>Wheel Spanner</b>	Present & Functioning
<b>Security Lock Nut</b>	N/A	<b>Run Flat Repair Kit</b>	N/A
<b>Comments</b>	Tools in order		

## UNDER CARRIAGE

<b>Steering System Play</b>	Good Working Condition	<b>Oil and Fluid Leaks</b>	Good Working Condition
<b>Exhaust Leaks</b>	Good Working Condition		
<b>Shocks (leaks) Front</b>	Good Working Condition	<b>Shocks (leaks) Rear</b>	Good Working Condition
<b>Springs/Suspension Bushes &amp; Links Front</b>	Good Working Condition	<b>Springs/Suspension Bushes &amp; Links Rear</b>	Good Working Condition
<b>Front Brakes – Disc's &amp; Pads</b>	Good Working Condition	<b>Rear Brakes – Disc's &amp; Pads</b>	N/A
<b>Brake Pipe Fitment</b>	Good Working Condition	<b>Rear Brakes – Drums &amp; Shoes</b>	Good Working Condition
<b>Front Wheel Bearings</b>	Good Working Condition	<b>Rear Wheel Bearings</b>	Good Working Condition
<b>Fuel Tank Leaks</b>	Good Working Condition	<b>Fuel Pipe Fitment</b>	Good Working Condition
<b>RF Tyre Tread</b>	More than 50%	<b>RF Tyre Size</b>	Correct as per OEM
<b>LF Tyre Tread</b>	More than 50%	<b>LF Tyre Size</b>	Correct as per OEM
<b>LR Tyre Tread</b>	More than 50%	<b>LR Tyre Size</b>	Correct as per OEM
<b>RR Tyre Tread</b>	More than 50%	<b>RR Tyre Size</b>	Correct as per OEM
		<b>Drive Shafts</b>	Good Working Condition
<b>Comments</b>	Undercarriage in order		

## TEST DRIVE

<b>Noise at Idle (Cold)</b>	Good Working Condition	<b>Excessive fumes/Smoke at idle</b>	Good Working Condition
<b>Final Drive Noise</b>	Good Working Condition	<b>Gearbox Noise</b>	Good Working Condition
<b>Engine Noise</b>	Good Working Condition	<b>Turbo/Super Charger Noise</b>	N/A
<b>Clutch Operation</b>	N/A	<b>Auto Gearbox Operation</b>	Good Working Condition
<b>Cruise Control/Adaptive</b>	N/A	<b>Instrument Cluster Functions</b>	Good Working Condition
<b>Warning Lights</b>	Good Working Condition	<b>Overheating</b>	Good Working Condition
<b>Engine Performance</b>	Good Working Condition	<b>Road holding / Stability</b>	Good Working Condition
<b>Brake Operation</b>	Good Working Condition	<b>Brake Noise</b>	Good Working Condition
<b>Brake Shudder</b>	No	<b>Emergency Stop Test / ABS</b>	Good Working Condition
<b>Steering Effort and Play</b>	Good Working Condition	<b>Suspension Noise</b>	No
<b>Vibrations &amp; Harshness over 110km/h</b>	No	<b>Handbrake function</b>	Good Working Condition
<b>Hot Restarting</b>	Good Working Condition	<b>Re-check Diagnostic Fault Codes</b>	No Fault Codes
<b>Comments</b>	Car drives great		

## GENERAL COMMENTS