

GENERAL

| | |
|-------------------|------------------------------------|
| Report Name | Botha & Deysel workshop - KG96LJGP |
| Client Name | Botha & Deysel workshop |
| Assessment Centre | Botha En Deysel Werkswinkel |
| Assessor | Hugo van Zyl |
| Inspection Date | 22-05-2026 12:20:20 |

VEHICLE


| | |
|------------------|------------------------------------|
| Year | 2018 |
| Reg No | KG96LJGP |
| Colour | White / Wit |
| VIN | SALWA2AK7KA424297 |
| Make | LAND ROVER |
| Model | RANGE ROVER SPORT 3.0D HSE (190KW) |
| Current Odometer | 143000 |
| Engine | 306DT1386787 |

CHECKS & REPORTS

| | | | |
|-----------------------------|---|------------------------------------|-------|
| OEM Warranty Active | False | Warranty Details | N/A |
| Aftermarket Warranty Active | False | Type Of Warranty | N/A |
| Service History | All Service Intervals completed by OEM or Aftermarket | Service History Invoices Available | False |
| Accident Damage Disclosure | None | Major Repair Disclosure | None |

BODY EXTERIOR

| | | | |
|------------------------------------|----------------------------|--------------------------------|------------------------|
| Number Plates | SABS Approved | Windscreen | No Cracks or Chips |
| Side Mirrors | No Damages or Paint Issues | Door Locks | Good Working Condition |
| Dents, Scratches and Misalignments | No Damages or paint issues | Wheel Nuts Torqued to OEM Spec | Yes; Torqued to Spec |



| | |
|----------|-------------------|
| Comments | Exterior in order |
|----------|-------------------|

STARTING AND CHARGING SYSTEM

| | | | |
|--------------------------------|--------------------------|---------------------------------|------------------------|
| Battery condition | Good Working Condition | Battery voltage normal 12.6 V | Good Working Condition |
| Battery Voltage Starting 9.6 V | Good Working Condition | Alternator Charging 13.5v - 15v | Good Working Condition |
| Comments | Starting system in order | | |

ENGINE COMPARTMENT

| | | | |
|--------------------------|-----------------------------|--------------------------------|------------------------|
| Bonnet Hinge | Good Working Condition | Bonnet Catch | Good Working Condition |
| Coolant Level | Good Working Condition | Radiator Cap | Good Working Condition |
| Hoses / Pipes | All Functioning, No Leaks | Auxiliary Drive Belts | Good Working Condition |
| Brake Fluid level | Good Working Condition | Engine oil level and Condition | Good Working Condition |
| Power Steering Oil level | Good Working Condition | Clutch Fluid (if separate) | N/A |
| Oil & Fluid Leaks | All Functioning, No Leaks | All Components Secured Safely | Good Working Condition |
| Comments | Engine compartment in order | | |

INTERIOR

| | | | |
|-------------------------------------|-----------------------------|--------------------------------------|------------------------|
| Ignition Lock; switch | Good Working Condition | Front Park Lights | Good Working Condition |
| Head lights - Dim | Good Working Condition | Head lights - Bright | Good Working Condition |
| Fog Lights Front | Good Working Condition | Rear Fog Lights | Good Working Condition |
| Rear Park Lights | Good Working Condition | Daytime Driving Lights | Good Working Condition |
| Reverse Lights | Good Working Condition | Stop Lights | Good Working Condition |
| Number Plate Light | Good Working Condition | Hazard Lights | Good Working Condition |
| LHS Indicator | Good Working Condition | RHS Indicator | Good Working Condition |
| Interior Lights | Good Working Condition | Controls/Switches | Good Working Condition |
| Instruments | Good Working Condition | Horn | Good Working Condition |
| Driver Window Mechanism | Good Working Condition | Passenger Window Mechanism | Good Working Condition |
| LHS Rear Window Mechanism | Good Working Condition | RHS Rear Window Mechanism | Good Working Condition |
| Sunroof Operation | Good Working Condition | Convertible Roof | N/A |
| LHS Mirror Adjustment | Good Working Condition | RHS Mirror Adjustment | Good Working Condition |
| Rear Wiper and Washer | Good Working Condition | Windscreen Wiper and Washer | Good Working Condition |
| Air Conditioner / HVAC System | Good Working Condition | Radio and Audio System | Good Working Condition |
| Driver Seat – Seat Belt | Good Working Condition | | |
| Driver Seat – Adjustments | Good Working Condition | Driver Seat – Upholstery | Good Working Condition |
| Passenger Seat – Seat Belt | Good Working Condition | | |
| Passenger Seat – Upholstery | Good Working Condition | Passenger Seat – Adjustments | Good Working Condition |
| Rear Passenger Seats – Seat Belt(s) | Good Working Condition | | |
| Rear Passenger Seats – Upholstery | Good Working Condition | Rear Passenger Seats – Adjustments | Good Working Condition |
| Panels, Covers and Trim Fitment | Good Working Condition | Diagnostic Fault Codes | Good Working Condition |
| Rear View Mirror | Good Working Condition | Roof Lining Fitment | Good Working Condition |
| Cabin Heater | Good Working Condition | Carpets and Mats | Good Working Condition |
| Set Clock | Good Working Condition | Check & Clear Diagnostic Fault Codes | Good Working Condition |
| Bonnet Release Lever | Good Working Condition | | |
| Comments | Interior in great condition | | |

BOOT

| | | | |
|--------------------------|------------------------|----------------------------|--------------------------------|
| Boot lock | Good Working Condition | Boot Hinges | Good Working Condition |
| Boot Linings | All correctly Fitted | Spare Wheel | More than 20% tread & inflated |
| Jack | Present & Functioning | Wheel Spanner | Present & Functioning |
| Security Lock Nut | Present & Functioning | Run Flat Repair Kit | N/A |
| Comments | Boot in order | | |

UNDER CARRIAGE

| | | | |
|--|------------------------|---|------------------------|
| Steering System Play | Good Working Condition | Oil and Fluid Leaks | Good Working Condition |
| Exhaust Leaks | Good Working Condition | | |
| Shocks (leaks) Front | Good Working Condition | Shocks (leaks) Rear | Good Working Condition |
| Springs/Suspension Bushes & Links Front | Good Working Condition | Springs/Suspension Bushes & Links Rear | Good Working Condition |
| Front Brakes – Disc's & Pads | Good Working Condition | Rear Brakes – Disc's & Pads | Good Working Condition |
| Brake Pipe Fitment | Good Working Condition | Rear Brakes – Drums & Shoes | N/A |
| Front Wheel Bearings | Good Working Condition | Rear Wheel Bearings | Good Working Condition |
| Fuel Tank Leaks | Good Working Condition | Fuel Pipe Fitment | Good Working Condition |
| RF Tyre Tread | More than 50% | RF Tyre Size | Correct as per OEM |
| LF Tyre Tread | More than 50% | LF Tyre Size | Correct as per OEM |
| LR Tyre Tread | More than 50% | LR Tyre Size | Correct as per OEM |
| RR Tyre Tread | More than 50% | RR Tyre Size | Correct as per OEM |
| | | Drive Shafts | Good Working Condition |
| Comments | Undercarriage in order | | |

TEST DRIVE

| | | | |
|--|------------------------|--|------------------------|
| Noise at Idle (Cold) | Good Working Condition | Excessive fumes/Smoke at idle | Good Working Condition |
| Final Drive Noise | Good Working Condition | Gearbox Noise | Good Working Condition |
| Engine Noise | Good Working Condition | Turbo/Super Charger Noise | Good Working Condition |
| Clutch Operation | N/A | Auto Gearbox Operation | Good Working Condition |
| Cruise Control/Adaptive | Good Working Condition | Instrument Cluster Functions | Good Working Condition |
| Warning Lights | Good Working Condition | Overheating | Good Working Condition |
| Engine Performance | Good Working Condition | Road holding / Stability | Good Working Condition |
| Brake Operation | Good Working Condition | Brake Noise | Good Working Condition |
| Brake Shudder | No | Emergency Stop Test / ABS | Good Working Condition |
| Steering Effort and Play | Good Working Condition | Suspension Noise | No |
| Vibrations & Harshness over 110km/h | No | Handbrake function | Good Working Condition |
| Hot Restarting | Good Working Condition | Re-check Diagnostic Fault Codes | No Fault Codes |
| Comments | Car drives great | | |

GENERAL COMMENTS