

## GENERAL

|                   |                                    |
|-------------------|------------------------------------|
| Report Name       | Botha & Deysel workshop - LS86DWGP |
| Client Name       | Botha & Deysel workshop            |
| Assessment Centre | Botha En Deysel Werkswinkel        |
| Assessor          | Hugo van Zyl                       |
| Inspection Date   | 15-07-2026 08:38:21                |


## VEHICLE

|                  |                              |
|------------------|------------------------------|
| Year             | 2024                         |
| Reg No           | LS86DWGP                     |
| Colour           | White                        |
| VIN              | ACVNRHR7K4154313             |
| Make             | ISUZU                        |
| Model            | D-MAX 250C FLEETSIDE S/C P/U |
| Current Odometer | 47891                        |
| Engine           | 4JK1ENG496                   |

## CHECKS & REPORTS

|                             |                                        |                                    |       |
|-----------------------------|----------------------------------------|------------------------------------|-------|
| OEM Warranty Active         | False                                  | Warranty Details                   | N/A   |
| Aftermarket Warranty Active | False                                  | Type Of Warranty                   | N/A   |
| Service History             | All service intervals completed by OEM | Service History Invoices Available | False |
| Accident Damage Disclosure  | None                                   | Major Repair Disclosure            | None  |

## BODY EXTERIOR

|                                    |                                                                                     |                                |                        |
|------------------------------------|-------------------------------------------------------------------------------------|--------------------------------|------------------------|
| Number Plates                      | SABS Approved                                                                       | Windscreen                     | No Cracks or Chips     |
| Side Mirrors                       | No Damages or Paint Issues                                                          | Door Locks                     | Good Working Condition |
| Dents, Scratches and Misalignments | No Damages or paint issues                                                          | Wheel Nuts Torqued to OEM Spec | Yes; Torqued to Spec   |
| Damage Mark Up                     |  |                                |                        |
| Comments                           | Good condition                                                                      |                                |                        |

STARTING AND CHARGING SYSTEM

|                                |                        |                                 |                        |
|--------------------------------|------------------------|---------------------------------|------------------------|
| Battery condition              | Good Working Condition | Battery voltage normal 12.6 V   | Good Working Condition |
| Battery Voltage Starting 9.6 V | Good Working Condition | Alternator Charging 13.5v - 15v | Good Working Condition |
| Comments                       | Good wo condition      |                                 |                        |

ENGINE COMPARTMENT

|                          |                              |                                |                        |
|--------------------------|------------------------------|--------------------------------|------------------------|
| Bonnet Hinge             | Acceptable Working Condition | Bonnet Catch                   | Good Working Condition |
| Coolant Level            | Good Working Condition       | Radiator Cap                   | Good Working Condition |
| Hoses / Pipes            | Minor Leaks                  | Auxiliary Drive Belts          | Good Working Condition |
| Brake Fluid level        | Good Working Condition       | Engine oil level and Condition | Good Working Condition |
| Power Steering Oil level | Good Working Condition       | Clutch Fluid (if separate)     | Good Working Condition |
| Oil & Fluid Leaks        | All Functioning, No Leaks    | All Components Secured Safely  | Good Working Condition |
| Comments                 | Good working condition       |                                |                        |

INTERIOR

|                                     |                        |                                      |                              |
|-------------------------------------|------------------------|--------------------------------------|------------------------------|
| Ignition Lock; switch               | Good Working Condition | Front Park Lights                    | Good Working Condition       |
| Head lights - Dim                   | Good Working Condition | Head lights - Bright                 | Good Working Condition       |
| Fog Lights Front                    | Good Working Condition | Rear Fog Lights                      | N/A                          |
| Rear Park Lights                    | Good Working Condition | Daytime Driving Lights               | Good Working Condition       |
| Reverse Lights                      | Good Working Condition | Stop Lights                          | Good Working Condition       |
| Number Plate Light                  | Good Working Condition | Hazard Lights                        | Good Working Condition       |
| LHS Indicator                       | Good Working Condition | RHS Indicator                        | Good Working Condition       |
| Interior Lights                     | Good Working Condition | Controls/Switches                    | Good Working Condition       |
| Instruments                         | Good Working Condition | Horn                                 | Good Working Condition       |
| Driver Window Mechanism             | Good Working Condition | Passenger Window Mechanism           | Good Working Condition       |
| LHS Rear Window Mechanism           | N/A                    | RHS Rear Window Mechanism            | N/A                          |
| Sunroof Operation                   | N/A                    | Convertible Roof                     | N/A                          |
| LHS Mirror Adjustment               | Good Working Condition | RHS Mirror Adjustment                | Good Working Condition       |
| Rear Wiper and Washer               | N/A                    | Windscreen Wiper and Washer          | Good Working Condition       |
| Air Conditioner / HVAC System       | Good Working Condition | Radio and Audio System               | Good Working Condition       |
| Driver Seat – Seat Belt             | Good Working Condition |                                      |                              |
| Driver Seat – Adjustments           | Good Working Condition | Driver Seat – Upholstery             | Good Working Condition       |
| Passenger Seat – Seat Belt          | Good Working Condition |                                      |                              |
| Passenger Seat – Upholstery         | Good Working Condition | Passenger Seat – Adjustments         | Good Working Condition       |
| Rear Passenger Seats – Seat Belt(s) | N/A                    |                                      |                              |
| Rear Passenger Seats – Upholstery   | N/A                    | Rear Passenger Seats – Adjustments   | N/A                          |
| Panels, Covers and Trim Fitment     | Good Working Condition | Diagnostic Fault Codes               | Acceptable Working Condition |
| Rear View Mirror                    | Good Working Condition | Roof Lining Fitment                  | Good Working Condition       |
| Cabin Heater                        | Good Working Condition | Carpets and Mats                     | Good Working Condition       |
|                                     |                        | Check & Clear Diagnostic Fault Codes | Acceptable Working Condition |
| Set Clock                           | Good Working Condition |                                      |                              |
| Bonnet Release Lever                | Good Working Condition |                                      |                              |
| Comments                            | Good condition         |                                      |                              |

**BOOT**

|                   |                        |                     |                                |
|-------------------|------------------------|---------------------|--------------------------------|
| Boot lock         | Good Working Condition | Boot Hinges         | Good Working Condition         |
| Boot Linings      | All correctly Fitted   | Spare Wheel         | More than 20% tread & inflated |
| Jack              | Present & Functioning  | Wheel Spanner       | Present & Functioning          |
| Security Lock Nut | N/A                    | Run Flat Repair Kit | N/A                            |
| Comments          | Good working condition |                     |                                |

**UNDER CARRIAGE**

|                                         |                        |                                        |                        |
|-----------------------------------------|------------------------|----------------------------------------|------------------------|
| Steering System Play                    | Good Working Condition | Oil and Fluid Leaks                    | Good Working Condition |
| Exhaust Leaks                           | Good Working Condition |                                        |                        |
| Shocks (leaks) Front                    | Good Working Condition | Shocks (leaks) Rear                    | Good Working Condition |
| Springs/Suspension Bushes & Links Front | Good Working Condition | Springs/Suspension Bushes & Links Rear | Good Working Condition |
| Front Brakes – Disc’s & Pads            | Good Working Condition | Rear Brakes – Disc’s & Pads            | N/A                    |
| Brake Pipe Fitment                      | Good Working Condition | Rear Brakes – Drums & Shoes            | Good Working Condition |
| Front Wheel Bearings                    | Good Working Condition | Rear Wheel Bearings                    | Good Working Condition |
| Fuel Tank Leaks                         | Good Working Condition | Fuel Pipe Fitment                      | Good Working Condition |
| RF Tyre Tread                           | More than 50%          | RF Tyre Size                           | Correct as per OEM     |
| LF Tyre Tread                           | More than 50%          | LF Tyre Size                           | Correct as per OEM     |
| LR Tyre Tread                           | More than 50%          | LR Tyre Size                           | Correct as per OEM     |
| RR Tyre Tread                           | More than 50%          | RR Tyre Size                           | Correct as per OEM     |
|                                         |                        | Drive Shafts                           | Good Working Condition |
| Comments                                | Good condition         |                                        |                        |

**TEST DRIVE**

|                                     |                        |                                 |                        |
|-------------------------------------|------------------------|---------------------------------|------------------------|
| Noise at Idle (Cold)                | Good Working Condition | Excessive fumes/Smoke at idle   | Good Working Condition |
| Final Drive Noise                   | Good Working Condition | Gearbox Noise                   | Good Working Condition |
| Engine Noise                        | Good Working Condition | Turbo/Super Charger Noise       | Good Working Condition |
| Clutch Operation                    | Good Working Condition | Auto Gearbox Operation          | N/A                    |
| Cruise Control/Adaptive             | N/A                    | Instrument Cluster Functions    | Good Working Condition |
| Warning Lights                      | Good Working Condition | Overheating                     | Good Working Condition |
| Engine Performance                  | Good Working Condition | Road holding / Stability        | Good Working Condition |
| Brake Operation                     | Good Working Condition | Brake Noise                     | Good Working Condition |
| Brake Shudder                       | No                     | Emergency Stop Test / ABS       | Good Working Condition |
| Steering Effort and Play            | Good Working Condition | Suspension Noise                | No                     |
| Vibrations & Harshness over 110km/h | No                     | Handbrake function              | Good Working Condition |
| Hot Restarting                      | Good Working Condition | Re-check Diagnostic Fault Codes | No Fault Codes         |
| Comments                            | Good condition         |                                 |                        |

**GENERAL COMMENTS**

Good condition